


Regional Municipality of Niagara Casablanca Boulevard and GO Station Access Environmental Assessment Environmental Study Report

APPENDIX L

Conceptual Tree Removal Mapping








TA.	10+800	TO S	STA.	11+20
T	REE INVE	ENTO	RY P	LAN

DWG No.

2



		NOTES/LEGEND	DRAFTING		
		1 THE POSITION OF POLE LINES, CONDUTS, WATERWANDS, SEWER AND OTHER UNDERGOUND AND OVERGROUND UTILITIES AND STRUCTURES IS NOT NECESSARLY SHOWN ON THE CONTRACT DRAWINGS AND, WHERE SHOWN, THE ACCURACY OF THE POSITION OF SUCH UTILITES AND STRUCTURES IS NOT GUARANTEED. BEFORE STARTING WORK, THE CONTRACTOR SHALL INFORM INSELF OF THE EXACT LOCATION OF ALL SUCH UTILITES AND STRUCTURES AND SHALL ASSUME	GCC		\
		BEFORE STARTING WORK, THE CONTRACTOR SHALL INFORM HINSELF OF THE EXACT LOCATION OF ALL SUCH UTILITIES AND STRUCTURES AND SHALL ASSUME ALL LUBRILITY FOR DAWAGE TO THEM.	DESIGN		"Nummer
			SMP	Niagara 10 D ogion	
		2 PROPERTY LINES WERE PLOTTED USING REGISTERED PLANS AND BARS LOCATED IN THE FIELD. TO VERIFY THE ACCURACY OF THESE PROPERTY LINES, A LEGAL SURVEY SHOULD BE PERFORMED PRIOR TO CONSTRUCTION.		Niagara 🔫 / Region	-
			CHECKED BY		DILLON
			SMP	PUBLIC WORKS	CONSULTING
ISSUED FOR YYYY-MM-D	d xxx		APPROVED BY		
REVISION DATE	INIT.		DPM		

00	CONSULTANT FILE No. 18-7650			
	TE	2018-10-24		
	ALE	AS SHOWN		
STA. 9+720 TO STA. 10+116				
TREE INVENTORY PLAN	F. No.	#		
DV	G No.		REV.	
		3	0	